



CAMS, Inc.
 14421 Airport Parkway
 Clearwater, Florida
 33762

INVOICE

Date	Invoice #
8/23/2012	7181

Bill To:

Pinellas Pilots Association
 PO BOX 17838
 Clearwater, FL 33762
 Attn: Mike Kutz



Registration #	N52633
Terms	Due on receipt
Tach	
Hobbs:	

QTY	Description	Sqw	Rate	Amount
	Additional requirements for installation of overhauled engine.			
6	Card heat box seal on valve is bad.	1	80.00	480.00T
2.3	Two sheet metal baffle repairs.	2	80.00	184.00T
0	Replace all low pressure hoses. (Insurance labor)	3	80.00	0.00T
7	Make and replace all high pressure hoses as required.	4	80.00	560.00T
1	Outside Repair - Oil cooler	5	200.00	200.00T
1	Engine overhaul		8,500.00	8,500.00T
4	Lord Engine Mount		175.00	700.00T
4	Engine Mount Nut		2.55	10.20T
1	Sheet Metal .032 Square Foot		21.00	21.00T
2	Mineral Spirits, per Gallon		11.00	22.00T
8	1/4 Hose		5.00	40.00T
5	3/8" hose		7.00	35.00T
4	1/2" LOW PRESSURE HOSE		5.00	20.00T
3	5/8 hose		8.00	24.00T
3	3/4" LP Hose		9.00	27.00T
4	SCAT hose 2" (one foot)		5.00	20.00T
20	Wire Loom 1/2" (per ft)		1.00	20.00T
1	Oil quick drain		42.75	42.75T
1	RTV Silicone (per tube)		14.95	14.95T
1	Florida discretionary tax		50.00	50.00

CAMS, Inc. appreciates your business, however balances overdue by 30 days or more will be subject to a 1.5% monthly finance charge. Again, thank you for your business.

Subtotal \$10,970.90

Sales Tax (6.0%) \$655.25

Total \$11,626.15

Payments/Credits \$-11,626.15

Balance Due ***\$0.00***

Phone #	Fax #
(727)507-8881	(727)507-8887